iJETRM
International Journal of Engineering Technology Research & Management

HAZARD IDENTIFICATION AND RISK ASSESSMENT IN GARMENT SEWING AND PACKING UNIT

Mr.S.P.Ramachandran[1]
Dr.K.Muthukumar[2]
[1]Student (Industrial Safety Engineering, Bannari Amman Institute of Technology, Tamil Nadu, India)
[2]Professor (Bannari Amman Institute of Technology, Tamil Nadu, India)

ABSTRACT
Hazard Identification and Risk Analysis were carried out in garment sewing and packing unit. Risk rating has been calculated from the point of view of the severity, probability and frequency of occurrence. Risk rating was been divided into three categories. Low, medium and high risk rating were assigned depending upon the severity of occurrence and categorized as 1 to 7, 8 to 14 and 15 to 20, respectively. It has been found from this study that there is medium risk associated in running a garment sewing and packing unit. Different control measures were identified and suggested to ensure safety of the workforce in the factory.

Keywords: Hazard, Risk, Low, Severity, Probability.

I. INTRODUCTION

The essential elements of the health and safety management system is hazard identification. It is the foundation for developing safe work procedures, establishing prevention programs and making other precautions to eliminate or control the hazards. A hazard is any source of potential damage, harm or adverse health effects on something or someone. Risk is the chance that a hazard will cause harm. Hazard identification process involves identifying both existing and potential workplace hazards, assessing the risks, determining and implementing the controls, and reviewing hazards.

Employers have the legal responsibility to identify and control, to the best of their ability, workplace hazards in order to protect workers. Likewise, workers have the right to know about the hazards of the job and how to protect themselves, and the responsibility to follow company rules that outline the hazard control processes. It is the responsibility of all workers to understand what a hazard is, what the risk is, how the hazards can affect people, property, and the environment, and how to prevent injury or illness from that hazard. Hazard identification of different activities in a garment sewing and packing unit has been carried out. Activities have been classified under several categories and risk assessment has been carried out based on the severity, probability and frequency of occurrence. Major activities and sub categories are listed below. This study is carried out and the way to reduce the risk is to be suggested.

II. Methodology

iJETRM
International Journal of Engineering Technology Research & Management

Fig1: HIRA process

III. HAZARD IDENTIFICATION AND RISK ASSESSMENT IN GARMENT SEWING AND PACKING UNIT

8.3 RiskAnalysis								
Severity **1 = Minor** **3 = seriously (normally reversible)** **6 = Major (normally not reversible)** **10=Fatal**	**Probability** **1=Unlikely** **2=Possible** **4 =Probable** **6=Certain**	**Frequency** **1 = No recorded Occurrence** **2=one occurrence** **3= two occurrences** **4=more than two occurrences**		**Risk Rating** **1-7= Low** **8-14=Medium** **15-20=High**				
Activity Description	Hazard	Who is at Risk	Controls	Severity 1-10(X)	Probability 1-6(Y)	Frequency 1-4(Z)	R.R X+Y+Z	Additional Controls

iJETRM
International Journal of Engineering Technology Research & Management

A. contact with machines								
Flat lock machines	Finger	Employees working in sewing machine	By providing the needle guard it prevents the operator from getting his/her hand beneath the needle.	3	1	1	5	Awareness given to employees about the needle guard.
Flatlock machines	Eye injury	Employeesworking insewingmachine	It prevents the brokenneedlethat fly offfrom the machine and hurting theuser.	6	1	1	8	Awareness given toemployees about theneedleguard.
Overlock machines	Finger	Employeesworking in thesewingmachine.	By providing theneedle guard itprevents the operatorfrom getting his/herhand beneath theneedle.	1	1	1	3	Awareness given toemployees about theSOP.
Overlock machines	Eyeinjury	Employees working in thesewing machine.	By providing theneedle guard which ismade up of glassmaterialtheviewof	6	2	1	9	Awareness given toemployees about theSOP.

iJETRM
International Journal of Engineering Technology Research & Management

StappingSinger	Finger	Employees working in thesewing machine.	By providing theneedle guard itprevents the operatorfrom getting his/herhand beneath theneedle.	1	2	1	4	Awareness given toemployees about theSOP.
Singer	Eyeinjury	Employees working in thesewing machine	By providing theneedle guard which ismade up of glassmateria ltheviewof	6	2	1	9	Awareness given toemployee s about theSOP.
Fusing	Finger	Employees working in hot press machine	By completely covering the hot surface it will avoid injury	1	2	1	4	Awareness given toemployee s about theSOP.
Stapping	Finger	Employees working in tag punching machine	By using proper PPE it will avoid injury	1	2	1	4	Awareness given to the employees about PPE
MECHANICAL DAMAGE TO SERVICES, PPE or Other item								
Tearing of hard gloves	Injury	Employees using PPE	Low usage	6	1	1	8	Awareness given to employess

iJETRM
International Journal of Engineering Technology Research & Management

								about the importance of using PPE
Face mask	Injury	Employees using PPE	Low usage	6	1	1	8	Awareness given to employess about the importance of using PPE
Ear plugs	Injury	Employees using PPE	Low usage	6	1	1	8	Awareness given to employess about the importance of using PPE
Falling object from height								
Falling of material from racks while handling	Major injury	Materials are placed in racks with proper hinged hooks with the wall	Materials are going to be arranged in horizontally sequence	6	1	1	8	Awareness given to employees about the risk involved
Fire /explosive								
Fire due to diesel storage	Major	All employees	Sufficient protection is to be provided	6	2	1	9	Awareness given to employees about do and don't

iJETRM
International Journal of Engineering Technology Research & Management

								in the area
Fire due to electrical short circuit	Major	All employees	Sufficient fire protection equipment is need to be providied	6	2	1	9	Awareness about do and don't s for electrical power points and connection
Fire due to waste storage	Major	All employees	Waste are disposed regularly and stored separately based on the property	6	2	1	9	Awareness about do and don't s for waste storage is given
Electrical								
Main control panel	Electrical shock	Electrical maintenance employee	All safety gadgets are need to be provided	6	2	1	9	Awareness given to employee about the handling and regular maintenance of control panel
Sub control panel	Electrical shock	Electrical maintenance employee	All safety gadgets are need to be provided	6	2	1	9	Awareness given to employee about the handling

iJETRM
International Journal of Engineering Technology Research & Management

								and regular maintenance of control panel
Distribution boards	Electrical shock	All the employees	All safety gadgets are need to be provided	6	2	1	9	Awareness given to employee about the handling and regular maintenance of control panel
Diesel generator								
Diesel generator	Fall down	Electrical maintenance employee	Proper bed for generator is need to be provided	6	1	2	9	Awareness is given to employee about the need for proper bed
Diesel generator LT cable	Electrical shock	Electrical maintenance employee	Proper wiring for generator is need to be provided	6	1	2	9	Awareness is given to employee about the need for proper wirings
Main control panel	Electrical shock	Electrical maintenance employee	All safety gadgets are need to be provided	6	2	1	9	Awareness given to employee about the handling and regular maintenance of control

iJETRM
International Journal of Engineering Technology Research & Management

								panel
compressor	Fire hazard	All employees	Separate room is to be provided with proper insulation	6	3	3	12	Awareness given to administrative controls
Noise								
Sewing area	Hearing damage	Employees working in department	Proper PPE is need to be provided	1	2	1	4	Awareness given to employess about importance of PPE
Diesel generator	Hearing damage	Employees working in department	Proper PPE is need to be provided	1	2	1	4	Awareness given to employess about importance of PPE
Psychological , social and medical								
Excessive time	Tiredness	All employees	Working hours need to be restricted and educated employees	6	1	1	8	Supervising department is instructed to monitor the working

iJETRM
International Journal of Engineering Technology Research & Management

								hours regularly
responsibility	Mental stress	All employees	Work pressure need to ne divided proper	6	1	1	8	Instructed to monitor and plan
First aid kit	Injury	All employees	First aid kit is need to be placed	6	1	2	9	Instructed to supervising department to place first aid kit in proper place
Facilty& infrastructure								
Shop floor lighting	Injury	All employees	Adequate lighting need to be provided	6	1	1	8	Preventive maintenanc e will ensure safe working area
Cracks in the wall	Major	All employees	Inspected in regular basis and action will be taken for reasons	6	1	1	8	
Corrosion in metal parts	Injury	All employees	Inspected in regular basis and action will be taken for reasons	6	1	1	8	Preventive maintenance will ensure safe working area

iJETRM
International Journal of Engineering Technology Research & Management

Water leakages in pipes	Injury	All employees	Inspected in regular basis and action will be taken for reasons	6	1	1	8	Preventive maintenance will ensure safe working area
Insufficient vehicle parking area	Injury	All employees	Sufficient parking area need provided	6	1	1	8	Preventive maintenance will ensure safe working area

IV. CONCLUSION:

Risk assessment in garment industry has been carried out in different areas ,physical ,chemical, manual handling and electrical hazards is been identified and the control measures are being suggested hierarchy of elimination, substitution, engineering controls, administrative measures and PPE . It is found that the hazard in compressor unit is high and also in generator area is high which requires immediate control measures. This study provides the awareness is given to employees and as well as administration.

REFERENCES:

1. Textile Business-JJG, “Hazard identification and risk assessment Standard”, March 2018.
2. D.S Padmini..,” Unsafe work environment in garments industries”, journal of environmental research and development, volume 7 no.1A 2012.
3. Thillainatarajan, “Review on Occupational Health Diseases in the textile industries”, International Research Journal of Engineering and Technology, Volume: 06 Issue: 10, Oct
4. NaziaMalik..,” Role of hazard control measure in occupational health and safety in the textile industry of Pakistan, Pak j.agri sci vol 47(1), 72-76,2010.
5. Hafiz Danish asraf.,”frequency of hearing loss among textile workers of wearing units in Karachi, Pakistan
. 6. Tiwari meenaxi..,” Causes of Musco- skeletal disorders in the textile industry”, Issn 2329-3563.vol 1(4),4850,December 2012.
7. Vasimkhatik..,” The pioneering study on identification of fire hazards in cotton ginning industries of nandurbar region of Maharashtra”, volume-2, Issn 2277-8179.
8. Nimkar2016,‘Chemical Safety at the Workplace in Textile Industry’ NimkarTek Technical Services Pvt Ltd.
9. Faisal Hannan 2015,Risk Assessment and Evaluation of Basic Health and Safety Facilities (